

11.	Nut	Brass	1	Nickel
10.	Washer	Brass	1	Nickel
9.	Gasket	Silicone	1	Black
8.	Braid Clamp	Brass	1	Nickel
7.	Nut	Brass	1	Nickel
6.	Shell	Brass	1	Nickel
5.	Retaining Ring	Brass	1	None
4.	Insulation	PTFE	1	White
3.	Pin	Brass	1	Gold
2.	Body	Brass	1	Nickel
1.	Body	Brass	1	Nickel
NO.	DESCRIPTION	MATERIAL	Q'TY	FINISH

ROHS COMPLIANT

		夏尼有限公司 SHINING PRECISION CO., LTD	
繪圖DRAWN	Jenny	SCALE	UNITS
審核CHECKED	<i>Peter</i>	比 例	單 位
主管APPROVAL	<i>Peter</i>	2:1	mm
圖名		公差TOLERANCE	
TITLE		X	±0.2
版次REV.		XX	±0.1
A		XXX	±0.05
電腦圖檔CAD FILE		ANGLE	±0.5°
日期DATE		U-Wi-213 TG	
C:/SHINING/UHF-PARTS/UHF-29B-1.DWG		2013.01.29	

Picture 1



Picture 2



Picture 3



Picture 4




The clamp must be placed between the copper-foil and the braid.


Picture 5




Picture 6



Picture 7



Picture 8



Picture 9



Please, do never forget to check, if there is a short circuit!